



**BMW 5: 1FGU429**

Vinnnumber:	<b>WBAFW11030C714746</b>	Versionname:	<b>5 BER 520d Start/Stop</b>
First Registrationdate:	<b>25/06/2013</b>	Fiscalpower:	<b>163PK</b>
Expertise Mileage:	<b>126418</b>	Power Kw:	<b>120</b>
Bodytype:		Body color	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>3127</b>
Maintenance	<b>IN 6000 KM</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>4</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar removable</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/17/97 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1036,74</b>
-------------------	----------------

Roof, Dent(s) and scratch(es), LI - Repair and paint (complete)	<b>0,00</b>
---	-------------



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	<b>254,16</b>
---	---------------



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Glove compartment lid, Scratch(es), Acceptable 0,00



Bumper F, Scratch(es), It - Spot repair 115,56



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Repaired, Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



