


FORD Grand C-Max: 1FCT474

Vinnnumber:	WF0HXWBPBHP41833	Versionname:	GR.C-MAX Trend St/St
First Registrationdate:	27/05/2013	Fiscalpower:	95PK
Expertise Mileage:	134273	Power Kw:	70
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3223
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Panoramic roof
GPS storage	Luggage cover
GPS storage	SD Rear parking sensors
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/99 H Steel			
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	848,68
-------------------	--------

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F L, Bad repair, Acceptable	0,00
----------------------------------	------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display


Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Brand badge R, Chemical pollution, Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Dent(s), PDR - Knock out without painting	63,00



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)	362,08
---	--------



Door R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80

