



BMW 5: 1HJH446

Vinnnumber:	WBA5E51030D673955	Versionname:	5 BER 520da 163PK Aut.
First Registrationdate:	1/08/2014	Fiscalpower:	
Expertise Mileage:	70999	Power Kw:	120
Bodytype:	Berline	Body color:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2201
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Total cost ex VAT	1988,41
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,16



Bonnet, Bad repair, Acceptable	0,00
--------------------------------	------

Bumper, Dent repair, Acceptable 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Door R R, Dent(s) and scratch(es), Le - Replace and paint 1107,49



Sill outer R, Scratch(es), LI - Repair and paint (complete) 372,60

