



FORD MONDEO: 1TJW169

| | | | |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnumber: | WF0FXXWPCFHD63367 | Versionname: | |
| First Registrationdate: | 22/11/2017 | Fiscalpower: | |
| Expertise Mileage: | 29559 | Power Kw: | 110 |
| Bodytype: | Break | Body color: | Dark Grey |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2205 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | |
| Seats F heated | |
| Radio multimedia | |
| Type of headlighting | Headlighting LED |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | |
|----------------------------------|-----------------------------|-----------------------------|--|
| 235/50/17/96 W LightMetal | | | |
| Summer tyres: | Fr.L. Goodyear: 5 mm | Fr.R. Goodyear: 5 mm | |
| | Re.L. Goodyear: 6 mm | Re.R. Goodyear: 6 mm | |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 369,84 |
|-------------------|--------|

| | |
|---|--------|
| Wing R R, Scratch(es), LI - Repair and paint (complete) | 369,84 |
|---|--------|



| | |
|---------------------------------------|------|
| Rear window, Scratch(es), E - Replace | 0,00 |
|---------------------------------------|------|



Bumper F, Bad repair, Acceptable 0,00

