


BMW X5: ZC6073

| | | | |
|-------------------------|--------------------------|--------------|-------------------------------------|
| Vinnnumber: | WBAKS210000H98464 | Versionname: | X5 2.0dA xDrive25 218PK Aut. |
| First Registrationdate: | 2/09/2014 | Fiscalpower: | |
| Expertise Mileage: | 91437 | Power Kw: | 160 |
| Bodytype: | SUV | Body color: | Silver |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2728 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | |
|--------------------------------|------------------------------|-------------------|
| Radio CD | Seats electric F L | |
| Windows electric F | Seats electric F R | |
| Windows electric R | Central consol F | |
| Cruise Control | Luggage cover | |
| Steering wheel multifunctional | Front parking sensors | |
| Seats F heated | Rear parking sensors | |
| Radio multimedia | Type of Tow bar | No Tow bar |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining leather | |
| Type of climate control | Autom climate control | |
| Sport seats | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|-----------------------|-------|-----------------------|
| | 255/55/18/109 V LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 7 mm | Fr.R. | Michelin: 7 mm |
| | Re.L. | Michelin: 7 mm | Re.R. | Michelin: 7 mm |

Assistance equipment

| | |
|------------|------------|
| Repair kit | Yes |
|------------|------------|

| | |
|-------------------------------------|------|
| Total cost ex VAT | 0,00 |
| Tailgate, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R R, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper F, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |