



MERCEDES A: 1KXB774			
Vinnumber:	WDD1760121V094103	Versionname:	1.5 A 180 CDI
First Registrationdate:	20/07/2015	Fiscalpower:	
Expertise Mileage:	175608	Power Kw:	80
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2727
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Steering wheel multifunction	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			438,00
Bumper moulding F L, Broken, E - Replace			14,40



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display