



PEUGEOT 308: 1HJH427

Vinnnumber:	VF3LB9HPAES139696	Versionname:	308 BER Active 92PK
First Registrationdate:	1/08/2014	Fiscalpower:	
Expertise Mileage:	140061	Power Kw:	68
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 6800KM	Parking lot:	3404
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2275,00
-------------------	----------------

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	220,18
---	---------------



License plate F, Deformed / Strained, E - Replace	20,00
---	--------------



Wing R L, Dent(s), PDR - Knock out without painting 75,00



Boot cover, Broken, E - Replace 10,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door panel R R, Stain, Cleaning 25,00



Armrest R M, Scratch(es), Smart repair 64,32



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 428,20



Door R R, Dent(s), PDR - Knock out without painting 87,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80

