



MERCEDES B: 1HJV565			
Vinnnumber:	WDD2462121J266453	Versionname:	B 180 CDI BE 109PK
First Registrationdate:	5/08/2014	Fiscalpower:	
Expertise Mileage:	20736	Power Kw:	80
Bodytype:	Hatchback	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2704
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining artificial leather
Type of climate control:	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Yokohama: 6 mm	Fr.R.	Yokohama: 6 mm
	Re.L.	Yokohama: 7 mm	Re.R.	Yokohama: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			306,80
Roof, Hail damage, LI - Repair and paint (complete)			0,00



Wing F R, Dent(s), Acceptable	0,00
--------------------------------------	-------------

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Bonnet, Hail damage, LI - Repair and paint (complete) 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

