



**MERCEDES V-klasse: 1HKG926**

Vinnnumber:	<b>WDF44781313005895</b>	Versionname:	<b>V-CLASSE MWB 220 CDI 163PK</b>
First Registrationdate:	<b>8/08/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>180630</b>	Power Kw:	<b>120</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2508</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>8</b>		
Number head rests:	<b>8</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F	
Windows electric F	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	<b>No Tow bar</b>
Radio multimedia		
Type of headlighting	<b>Headlighting LED</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/17/101 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Hankook: 5 mm</b>	Re.R.	<b>Hankook: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	<b>2494,46</b>
-------------------	----------------

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	<b>308,20</b>
---	---------------



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	<b>318,35</b>
---	---------------



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Dent(s), LI - Repair and paint (complete) 301,68



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Crack, Le - Replace and paint 651,00



Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80

