



OPEL Astra: 1FPZ452

Vinnumber:	W0LPC8EWXE8004873	Versionname:	ASTRA BRE ecoFLEX Essentia S&S 110PK
First Registrationdate:	19/09/2013	Fiscalpower:	
Expertise Mileage:	78680	Power Kw:	81
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2710
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/50/16/95 H Steel			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1315,21







Roof, Dent(s), PDR - Knock out without painting 63,00



Wing R R, Bad repair, Acceptable 0,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08

	Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	Door R R, Bad repair, Acceptable	0,00
	Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
	Wing R L, Bad repair, Acceptable	0,00
	Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
	Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	220,18
	Tailgate, Scratch(es), Acceptable	0,00

No pictures to display