


**OPEL MOKKA: 1THL247**

Vinnnumber:	<b>W0LJC7EL9FB038507</b>	Versionname:	<b>1.7 CDTI 96KW ECOFLEX S/S ENJOY</b>
First Registrationdate:	<b>30/06/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>79390</b>	Power Kw:	<b>96</b>
Bodytype:	<b>SUV</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2211</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/60/17/96 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 2 mm</b>	Fr.R.	<b>Continental: 2 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	779,63
Internal Boot Lining R, Scratch(es), Smart repair	110,64



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------





Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), E - Replace 84,00



Door panel F L, Scratch(es), E - Replace 114,00



Bumper spoiler F, Scratch(es), E - Replace 42,00



Internal Boot Lining L, Scratch(es), Smart repair 110,64



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display