


MERCEDES Vito: 1CV0778

Vinnnumber:	WDF63960113723237	Versionname:	VITO 110 B/F SWB 95PK
First Registrationdate:	7/03/2012	Fiscalpower:	
Expertise Mileage:	125219	Power Kw:	70
Bodytype:	Transporter	Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2601
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Central consol F	
Windows electric F		Front parking sensors	
Type of headlighting	Headlighting Halogen	Rear parking sensors	
Type of GPS	No GPS	Type of Tow bar	No Tow bar
Type of Lining	Lining artificial leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/16/104 R Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
		Jack	Yes

Total cost ex VAT	760,88
Backrest cover F L, Hole, E - Replace	300,00





Door F L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Sill outer L, Dent(s), LI - Repair and paint (complete)	232,88
---	--------



Bumper corner R R, Scratch(es), Acceptable	0,00
--	------

<i>No pictures to display</i>		
Windscreen, Tear, E - Replace		0,00
		
Glove compartment lid, Broken, E - Replace		228,00
		
Door F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		