



NISSAN Qashqai: 1HNU887			
Vinnnumber:	<b>SJNFAAJ11U1178157</b>	Versionname:	<b>QASHQAI 2WD Tekna 110PK</b>
First Registrationdate:	<b>1/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>157975</b>	Power Kw:	<b>81</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3324</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options			
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunction		Rear parking sensors	
Seats F heated		Type of Tow bar	<b>Tow bar fixed</b>
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>225/45/19/96 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Firestone: 5 mm</b>	Fr.R.	<b>Firestone: 5 mm</b>
	Re.L.	<b>Firestone: 4 mm</b>	Re.R.	<b>Firestone: 4 mm</b>

Assistance equipment			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>1912,22</b>
Door R R, Scratch(es), LI - Repair and paint (complete)			<b>318,35</b>



Bumper R, Scratch(es), Smart repair	<b>110,64</b>
-------------------------------------	---------------



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00




Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical pollution, LI - Repair and paint (complete) 250,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00

No pictures to display

Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Internal Boot Lining L, Broken, E - Replace 64,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Protection plate M, Deformed / Strained, E - Replace 64,00

