



VOLKSWAGEN Golf: 1FPZ462

Vinnumber:	WVWZZZAUZEW109623	Versionname:	GOLF BER Trendline 90PK
First Registrationdate:	19/09/2013	Fiscalpower:	
Expertise Mileage:	149161	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3730
Maintenance	IN 3900 KM OF 16 DAGEN		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	626,55
Seat cover R R, Stain, Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35



Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20

