



## VOLKSWAGEN Passat: 1HAG020

Vinnnumber:	<b>WVWZZZ3CZEE168526</b>	Versionname:	<b>PASSAT BER Comfortline BMT 105PK</b>
First Registrationdate:	<b>3/06/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>169865</b>	Power Kw:	<b>77</b>
Bodytype:		Body color	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>2202</b>
Maintenance	<b>25000 KM OU 311 JOURS</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>4</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

## Options

Radio CD		Sun Roof electric
GPS storage	<b>HD</b>	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>215/55/16/93 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Kleber: 4 mm</b>	Fr.R.	<b>Kleber: 4 mm</b>
	Re.L.	<b>Kleber: 6 mm</b>	Re.R.	<b>Kleber: 6 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	683,03
-------------------	--------

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00
---	------



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Door F R, Scratch(es), LI - Repair and paint (complete)	0,00
---	------



Tailgate, Dent(s), LI - Repair and paint (complete)	301,68
---	--------



Wing R L, Dent(s), PDR - Knock out without painting	63,00
---	-------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Door R L, Dent(s) and scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

*No pictures to display*