



**VOLKSWAGEN Passat: 1HJK307**

|                                    |                          |              |   |
|------------------------------------|--------------------------|--------------|---|
| Vinnnumber:                        | <b>WVWZZZ3CZFE027021</b> | Versionname: | <b>PASSAT VAR Comfortline BMT 105PK</b> |
| First Registrationdate:            | <b>1/08/2014</b>         | Fiscalpower: |   |
| Expertise Mileage:                 | <b>127283</b>            | Power Kw:    | <b>77</b>                               |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Dark Grey</b>                        |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                          |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                        |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                               |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3609</b>                             |
| Number of doors:                   | <b>5</b>                 |              |   |
| Number of seats:                   | <b>5</b>                 |              |   |
| Number head rests:                 | <b>5</b>                 |              |   |
| Rims summer:                       | <b>Aluminium</b>         |              |   |
| Category:                          | <b>Passenger Car</b>     |              |   |
| Oil level:                         | <b>OK</b>                |              |   |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |   |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Sun Roof electric            |
| Windows electric F             | Central consol F             |
| Windows electric R             | Luggage cover                |
| Cruise Control                 | Front parking sensors        |
| Steering wheel multifunctional | Rear parking sensors         |
| Seats F heated                 |                              |
| Radio multimedia               |                              |
| Type of headlighting:          | <b>Headlighting Halogen</b>  |
| Type of GPS:                   | <b>GPS big screen color</b>  |
| Type of Lining:                | <b>Lining leather</b>        |
| Type of climate control:       | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>215/55/16/97 H LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                            | <b>Continental: 5 mm</b> | Fr.R. | <b>Continental: 5 mm</b> |
|               | Re.L.                            | <b>Continental: 6 mm</b> | Re.R. | <b>Continental: 6 mm</b> |

**Assistance equipment**

|             |            |      |            |
|-------------|------------|------|------------|
| Spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-------------|------------|------|------------|

Total cost ex VAT 211,80

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F L, Dent(s), Acceptable 0,00

|  |      |
|--|------|
| <i>No pictures to display</i>                      |      |
| Rearview mirror housing R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>                      |      |
| Tailgate, Scratch(es), Acceptable                  | 0,00 |
| <i>No pictures to display</i>                      |      |