



VOLKSWAGEN Transporter: 1FH0250

Vinnnumber:	WV1ZZZ7HZEX002173	Versionname:	TRANSP.1200 B/F SWB
First Registrationdate:	1/07/2013	Fiscalpower:	140PK
Expertise Mileage:	54166	Power Kw:	103
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3215
Maintenance:	UITVOEREN		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	2		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Front parking sensors
Windows electric F	Rear parking sensors
Cruise Control	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/65/16/107 T Steel			
Summer tyres:	Fr.L.	Hankook: 7 mm	Fr.R.	Hankook: 7 mm
	Re.L.	Hankook: 9,9 mm	Re.R.	Hankook: 9,9 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2631,09
-------------------	---------

Maintenance, Maintenance, Execute	0,00
-----------------------------------	------


No pictures to display

Reflector, Broken, E - Replace	25,00
--------------------------------	-------



Tailgate, Dent(s) and scratch(es), Le - Replace and paint 799,99





Rearview mirror housing R, Scratch(es), Smart repair 110,64



Sidewall FL (LCV), Dent(s) and scratch(es), LI - Repair and paint (complete) 400,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Smart repair 110,64



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Bumper R, Deformed / Strained, E - Replace 329,40



Bumper F, Scratch(es), Smart repair 110,64

Bumper r, scratches, Smart repair

110,04



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

506,02

