


**AUDI A3: 1HBV864**

Vinnnumber:	<b>WAUZZZ8V5EA161248</b>	Versionname:	<b>A3 SB Attraction 105PK</b>
First Registrationdate:	<b>13/06/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>76680</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3312</b>
Maintenance:	<b>IN 15000KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/5/16/91 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Pirelli: 6 mm</b>	Re.R.	<b>Pirelli: 6 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	876,50
-------------------	--------

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Door F R, Dent(s), PDR - Knock out without painting	111,00
---	--------



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	220,18
---	--------


	Roof, Dent(s), Acceptable	0,00
No pictures to display		

Trunk lid covering R, Scratch(es), Smart repair	110,64
---	--------

	Door frame R L, Dent(s), It - Spot repair	115,56
--	---	--------

	Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--	--------

	Ceiling, Dirty, Cleaning	25,00
---	--------------------------	-------

	Bumper F L, Scratch(es), It - Spot repair	115,56
---	---	--------

	Door R R, Dent(s), PDR - Knock out without painting	63,00
--	---	-------

		
--	--	--