



AUDI A4: 1FON496			
Vinnnumber:	<b>WAUZZZ8K5EN011140</b>	Versionname:	<b>A4 BER TDi Multitr.136PK Aut.</b>
First Registrationdate:	<b>6/09/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>85843</b>	Power Kw:	<b>100</b>
Bodytype:		Body color	<b>Dark Brown</b>
Gearbox:	<b>Automatic</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>1207</b>
Number of doors	<b>4</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

Options			
Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear			
Summer tyres:	<b>225/55/16/95 Y LightMetal</b>		
	Fr.L.	Fr.R.	
	<b>Continental: 3 mm</b>	<b>Continental: 3 mm</b>	
	Re.L.	Re.R.	
	<b>Continental: 5 mm</b>	<b>Continental: 5 mm</b>	

Assistance equipment	
Emergency spare wheel	<b>Yes</b>

Total cost ex VAT	1426,40
Door F R, Scratch(es), LI - Repair and paint (complete)	318,35



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Wing F R, Bad repair, Acceptable 0,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35

