


BMW 3: 1HPX075

Vinnumber:	WBA3L11010K177019	Versionname:	3 TOURING 320d
First Registrationdate:	9/09/2014	Fiscalpower:	Eff.Dyn.Ed. 163PK
Expertise Mileage:	120252	Power Kw:	120
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4631
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunction			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	0,00
-------------------	-------------


Door R R, Dent(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Roof pillar L, Hail damage, PDR - Hail	0,00
--	-------------



Bonnet, Hail damage, PDR - Hail	0,00
---------------------------------	-------------



Bumper R, Dent(s) and scratch(es), Le - Replace and paint 0,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Rearlight R , Scratch(es), Acceptable 0,00

No pictures to display

Roof, Hail damage, PDR - Hail 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Hail damage, PDR - Hail 0,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display