


BMW 5: 1FQD648

Vinnumber:	WBA5C11000D035256	Versionname:	5 BER 518d 136PK
First Registrationdate:	20/09/2013	Fiscalpower:	
Expertise Mileage:	143894	Power Kw:	100
Bodytype:	Berline	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	SINDS 08-2018	Parking lot:	3508
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Front parking sensors	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Continental: 2,3 mm	Re.R.	Continental: 2,3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	153,32
--------------------------	---------------

Door F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Windscreen, Stone chip(s), Acceptable	0,00
--	-------------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door R L, Dent(s), Acceptable	0,00
--------------------------------------	-------------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Roof rack carrier R.M. Demond. Smart access	64,00
--	--------------

Backrest cover K M, Damaged, Smart repair 89,32



Protection plate M, Hole, E - Replace 89,00



Maintenance, Maintenance, Execute 0,00

No pictures to display