


**AUDI A6 Allroad: 1FKI056**

Vinnnumber:	<b>WAUZZZ4G7EN027521</b>	Versionname:	<b>A6 ALLROAD Quattro Tiptr.313PK Aut.</b>
First Registrationdate:	<b>25/07/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>161907</b>	Power Kw:	<b>230</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2706</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Sport seats			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>235/55/18/100 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Vredestein: 3 mm</b>	Fr.R.	<b>Vredestein: 3 mm</b>
	Re.L.	<b>Vredestein: 4 mm</b>	Re.R.	<b>Vredestein: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>
-----------------------	------------

Total cost ex VAT	<b>1514,48</b>
-------------------	----------------

Windscreen, Crack, E - Replace	<b>0,00</b>
--------------------------------	-------------



Alloy rim R L, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Sill outer R, Deformed / Strained, LI - Repair and paint (complete) 372,60



Ignition key, Missing, E - Replace 150,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Deformed / Strained, Le - Replace and paint 862,80



Bumper grille F R, Missing, E - Replace 34,08



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display