



## CITRO?N Berlingo: 1EFN111

Vinnumber:	<b>VF77J9HN0CJ664085</b>	Versionname:	<b>BERLINGO Attraction 75PK</b>
First Registrationdate:	<b>16/11/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>97889</b>	Power Kw:	<b>55</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3402</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

## Options

Radio CD		Type of Tow bar	<b>Tow bar fixed</b>
Windows electric F			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/65/15/92 H Steel</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 3 mm</b>	Fr.R.	<b>Uniroyal: 3 mm</b>
	Re.L.	<b>Uniroyal: 4 mm</b>	Re.R.	<b>Uniroyal: 4 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	2699,02
Bumper R, Scratch(es), Smart repair	110,64



Windscreen, Stone chip(s), E - Replace	395,40
--	--------



Bonnet, Rust, LI - Repair and paint (complete)	217,56
--	--------



Internal Boot Lining L, Scratch(es), Smart repair 110,64



Tailgate, Scratch(es), It - Spot repair 115,56



Ceiling, Stain, Cleaning 25,00



Rearview mirror R complete, Crack, E - Replace 138,00



Spare wheel compartment lining R L, Scratch(es), Smart repair 110,64



Wheel cover F R, Scratch(es), E - Replace 22,50



Internal Boot Lining R, Scratch(es), Smart repair 110,64



Bumper F, Dent(s), E - Replace 398,40



Boot carpet, Hole, E - Replace 75,00



Door panel F L, Scratch(es), E - Replace

91,50



Rear bulkhead lining, Scratch(es), E - Replace

62,00



Brand badge R, Missing, E - Replace

15,00



Tailgate, Dent(s), LI - Repair and paint (complete)

410,02



Seat cover R, Scratch(es), Smart repair

64,32



Steering wheel, Worn, Acceptable

0,00



Sill outer L, Scratch(es), It - Spot repair

115,56



Spare wheel compartment lining R R, Scratch(es), Smart repair

110,64

