



BMW 1: 1ETY924

Vinnumber:	WBA1C91030J508713	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	20/03/2013	Fiscalpower:	
Expertise Mileage:	74227	Power Kw:	85
Bodytype:	Hatchback	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1106
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	205/55/16/91 W Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1089,04
--------------------------	----------------

Roof pillar L, Scratch(es), LI - Repair and paint (complete)	220,18
---------------------------------------------------------------------	---------------



Wheel cover R L, Scratch(es), E - Replace	30,00
--------------------------------------------------	--------------



Rear spoiler, Scratch(es), LI - Repair and paint (complete) 115,56



Wheel cover F R, Scratch(es), E - Replace 30,00



Door F L, Repaired, Acceptable 0,00

No pictures to display
Door R L, Repaired, Acceptable 0,00

No pictures to display
Roof, Scratch(es), LI - Repair and paint (complete) 481,50



Bumper R, Chemical pollution, LI - Repair and paint (complete) 211,80



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display