


**BMW 3: 1HTC456**

|                                    |                          |              |                             |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnnumber:                        | <b>WBA3K91010F936102</b> | Versionname: | <b>3 TOURING 316d 116PK</b> |
| First Registrationdate:            | <b>25/09/2014</b>        | Fiscalpower: |                             |
| Expertise Mileage:                 | <b>154875</b>            | Power Kw:    | <b>85</b>                   |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Dark Blue</b>            |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>              |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>            |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                   |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3110</b>                 |
| Number of doors:                   | <b>5</b>                 |              |                             |
| Number of seats:                   | <b>5</b>                 |              |                             |
| Number head rests:                 | <b>5</b>                 |              |                             |
| Rims summer:                       | <b>Aluminium</b>         |              |                             |
| Category:                          | <b>Passenger Car</b>     |              |                             |
| Oil level:                         | <b>OK</b>                |              |                             |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                             |

**Options**

|                                |                              |                      |                          |
|--------------------------------|------------------------------|----------------------|--------------------------|
| Radio CD                       |                              | Central consol F     |                          |
| Windows electric F             |                              | Luggage cover        |                          |
| Windows electric R             |                              | Rear parking sensors |                          |
| Cruise Control                 |                              | Type of Tow bar      | <b>Tow bar removable</b> |
| Steering wheel multifunctional |                              |                      |                          |
| Radio multimedia               |                              |                      |                          |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                      |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                          |
| Type of Lining                 | <b>Lining leather</b>        |                      |                          |
| Type of climate control        | <b>Autom climate control</b> |                      |                          |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/60/16/92 H LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Michelin: 5 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|               | Re.L.                            | <b>Goodyear: 5 mm</b> | Re.R. | <b>Goodyear: 5 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                                   |      |
|-----------------------------------|------|
| Total cost ex VAT                 | 0,00 |
| Door R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>     |      |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>     |      |