



CITRO?N C4 Picasso: 1HSR506

Vinnnumber:	VF73AAHXTEJ766489	Versionname:	GR.C4 PICASSO BlueHDi Intens.150PK Aut.
First Registrationdate:	23/09/2014	Fiscalpower:	
Expertise Mileage:	153529	Power Kw:	110
Bodytype:	MPV	Body color:	Red
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3604
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F	
Windows electric R	Luggage cover	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	No Tow bar
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/95 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	900,00
-------------------	---------------

Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	-------------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	-------------

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00

