



CITROEN C4 Picasso: 1ANV780

Vinnnumber:	VF7UA9HR8BJ532247	Versionname:	GR.C4 PICASSO 7pl.Business GPS FAP 112PK
First Registrationdate:	17/02/2011	Fiscalpower:	
Expertise Mileage:	118262	Power Kw:	82
Bodytype:	MPV	Body color	White
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	3621
Battery functioning	Yes		
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 V LightMetal			
Summer tyres:	Fr.L.	Pirelli: 3,5 mm	Fr.R.	Pirelli: 3,5 mm
	Re.L.	Bridgestone: 2,6 mm	Re.R.	Bridgestone: 2,6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1097,76
-------------------	----------------

Seat cover F L, Deformed / Strained, Acceptable	0,00
---	-------------



Internal Boot Lining L, Scratch(es), Smart repair	110,64
---	---------------



Wing R L, Repaired, Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00

No pictures to display

Wing R R, Repaired, Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Dashboard, Scratch(es), Smart repair 110,64



Supplementary brake lights, Scratch(es), Acceptable 0,00

No pictures to display

Outer backrest protection R, Scratch(es), Smart repair 110,64



Internal Boot Lining R, Scratch(es), Smart repair 110,64



Brand badge R, Missing, E - Replace 24,00



Interior, Stain, Cleaning 25,00



Sill outer R, Dent(s), Acceptable 0,00

No pictures to display

Door R R, Repaired, Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Outer backrest protection L, Scratch(es), Smart repair 110,64



Roof, Rust, Acceptable 0,00

