



**PEUGEOT 308 BREAK: 1HFG385**

Vinnumber:	<b>VF3LC9HPAES149651</b>	Versionname:	
First Registrationdate:	<b>7/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>139595</b>	Power Kw:	<b>68</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4723</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Luggage cover
Windows electric F		
Cruise Control		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	
Level control		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 H Steel</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 6 mm</b>	Fr.R.	<b>Uniroyal: 6 mm</b>
	Re.L.	<b>Uniroyal: 6 mm</b>	Re.R.	<b>Uniroyal: 6 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT 64,32

Bumper R, Scratch(es), Acceptable 0,00



Door catch R L, Not functioning (well), P - Check 0,00




Door R L, Scratch(es), Acceptable 0,00



Floor covering F L, Worn, Acceptable

0,00



Wheel cover R R, Scratch(es), Acceptable

0,00



Door F L, Scratch(es), Acceptable

0,00



Ceiling, Burned, Smart repair

64,32



Door R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F R, Scratch(es), Acceptable

0,00



Covering interior front pillar L, Scratch(es), Acceptable

0,00



Door seal F R, Deformed / Strained, Acceptable

0,00

