



OPEL Astra: 1BEW997			
Vinnumber:	WOLPD8EG8B8083137	Versionname:	ASTRA BRE ECOTEC Enjoy FAP 110PK
First Registrationdate:	16/05/2011	Fiscalpower:	
Expertise Mileage:	132820	Power Kw:	81
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1232
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	215/60/16/95 H Steel			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	516,92
Rear window, Scratch(es), E - Replace	0,00



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R L, Scratch(es), It - Spot repair	115,56
---	--------



Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Trunk lid covering R, Broken, E - Replace	74,00
---	-------



Rocker panel inner F L, Dent(s), LI - Repair and paint (complete)	115,56
---	--------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display