


RENAULT Grand Scenic: 1FFI007

Vinnnumber:	VF1JZ09B349075046	Versionname:	GRAND SCENIC Dynamique 7pl.EDC 110PK Aut
First Registrationdate:	13/06/2013	Fiscalpower:	
Expertise Mileage:	155838	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	UITVOEREN	Parking lot:	1119
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Total cost ex VAT	5485,23
Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18




Gear shift lever knob, Worn, Acceptable


0,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50



Roof pillar L, Chemical pollution, It - Spot repair 115,56




Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Rear window, Scratch(es), E - Replace 0,00



Sill trim R L, Missing, E - Replace 10,00



Seat cover R L, Hole, E - Replace 360,00




Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Door frame R R, Scratch(es), It - Spot repair 115,56



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68





Maintenance, Maintenance, Execute 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Separation net, Deformed / Strained, E - Replace 114,00



Side window trim F R, Missing, E - Replace 25,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display

Separation net, Deformed / Strained, E - Replace 90,00





Door frame F L, Scratch(es), It - Spot repair

115,56



Interior, Dirty, Cleaning

25,00



Tyre F R, Hole, E - Replace

132,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Seat cover F L, Damaged, Acceptable

0,00



Foglight L, Deformed / Strained, E - Replace

138,00



Door frame F L, Scratch(es), It - Spot repair

115,56

Door frame R L, Scratch(es), II - Spot repair 115,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08

