



MERCEDES GLA: 1HSX455			
Vinnumber:	WDC1569081J053085	Versionname:	GLA 200 CDI 136PK
First Registrationdate:	24/09/2014	Fiscalpower:	
Expertise Mileage:	77662	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3528
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	235/50/18/97 V LightMetal			
Summer tyres:	Fr.L.	Dunlop: 3 mm	Fr.R.	Dunlop: 3 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 6 mm

Assistance equipment	
Repair kit	No
Compressor	Yes
Total cost ex VAT	1596,68
Tyre repair kit, Missing, E - Replace	252,64

<i>No pictures to display</i>	
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02





Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Spoiler F R, Scratch(es), E - Replace 48,00



Alloy rim R R polished, Scratch(es), Acceptable 0,00

No pictures to display

Luggage space cover, Damaged, E - Replace 288,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Sill trim R, Scratch(es), E - Replace 149,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper trim R, Dent(s), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display