



| VOLVO XC60: 1SSA780 | | | |
|-----------------------------------|--------------------------|--------------|---------------------------|
| Vinnnumber: | YV1DZARC1H2183514 | Versionname: | D3 Dynamic Edition |
| First Registrationdate: | 30/06/2017 | Fiscalpower: | |
| Expertise Mileage: | 38678 | Power Kw: | 110 |
| Bodytype: | SUV | Body color | Light Blue |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | OK |
| Battery functioning | Yes | Parking lot | 3602 |
| Number of doors | 5 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

| Options | | | |
|--------------------------------|------------------------------|-----------------------|--------------------------|
| Radio CD | | Sun Roof electric | |
| Windows electric F | | Panoramic roof | |
| Windows electric R | | Central consol F | |
| Cruise Control | | Luggage cover | |
| Steering wheel multifunctional | | Front parking sensors | |
| Radio multimedia | | Rear parking sensors | |
| Type of headlighting | Headlighting Halogen | Type of Tow bar | Tow bar removable |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| Degree of wear | | | | |
|----------------|-----------------------------------|--------------------------|-------|--------------------------|
| | 235/60/18/103 V LightMetal | | | |
| Summer tyres: | Fr.L. | Continental: 6 mm | Fr.R. | Continental: 6 mm |
| | Re.L. | Continental: 7 mm | Re.R. | Continental: 7 mm |

| Assistance equipment | | | |
|---|------------|------|---------------|
| Emergency spare wheel | Yes | Jack | Yes |
| Total cost ex VAT | | | 364,80 |
| Bumper F L, Deformed / Strained, Smart repair | | | 110,64 |



| | |
|---|---------------|
| Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 254,16 |
|---|---------------|



