



VOLVO XC60: XW5404

Vinnnumber:	YV1DZARC1H2070279	Versionname:	2.0 D3 2WD SUMMUM
First Registrationdate:	27/01/2017	Fiscalpower:	
Expertise Mileage:	41765	Power Kw:	110
Bodytype:	SUV	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2625
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	255/45/20/105 V LightMetal			
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	765,60
-------------------	--------

Alloy rim R R polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door R R, Scratch(es), 67 - Polish	0,00
------------------------------------	------

No pictures to display

Vanity mirror, Unclashed, E - Replace	84,00
---------------------------------------	-------



Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Certificate Of Conformity, Missing, E - Replace	150,00
---	--------

No pictures to display

Alloy rim R L polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper corner R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim F L polished, Deformed / Strained, E - Replace	277,44
--	--------

