



VOLVO XC60: 1HLG075

Vinnnumber:	YV1DZ31A1F2652711	Versionname:	XC60 D3 Kinetic 136PK
First Registrationdate:	19/08/2014	Fiscalpower:	
Expertise Mileage:	124233	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3333
Maintenance:	SERVICE IN 22731KM 8M		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/17/104 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Uniroyal: 8 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			0,00
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Sill trim R, Chemical polution, Acceptable			0,00
<i>No pictures to display</i>			
Door F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F R, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Wing R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Roof pillar R, Scratch(es), Acceptable			0,00

No pictures to display

Windscreen, Repaired, Acceptable

0,00

No pictures to display