



VOLVO V40: 1HUB011			
Vinnnumber:	YV1MV8481F2200656	Versionname:	V40 D2 Base 115PK
First Registrationdate:	2/10/2014	Fiscalpower:	
Expertise Mileage:	1	Power Kw:	84
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Oil level:	NOT OK
Fueltype:	Diesel		
Maintenance	12752KM		
Maintenance	OK		
Battery functioning	No		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Category	Passenger Car		
Oil level	NOT OK		
Registration Certificate Car (BE)	No		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Engine startingtime	NOT OK	Battery functioning	No

Degree of wear			
Summer tyres:	205/55/16/91 H LightMetal		
	Fr.L.	Fr.R.	Michelin: 6 mm
	Re.L.	Re.R.	Michelin: 5 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes
Total cost ex VAT	265,56
Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Certificate Of Conformity, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Door F L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Engine, Not functioning (well), Acceptable	0,00





Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), 67 - Polish	0,00



Alloy rim F R, Scratch(es), I - Repair	0,00
--	------



Bumper F, Scratch(es), It - Spot repair	115,56
---	--------



Door R R, Scratch(es), 67 - Polish	0,00
------------------------------------	------

