



**VOLKSWAGEN Polo: 1HPL859**

Vinnumber:	<b>WVWZZZ6RZFY070862</b>	Versionname:	<b>POLO Trendline BMT 90PK</b>
First Registrationdate:	<b>5/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>88387</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3104</b>
Maintenance:	<b>IN 20200KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Luggage cover	
GPS storage		Front parking sensors	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>175/70/14/84 T Steel</b>			
Summer tyres:	Fr.L.	<b>Fulda: 5 mm</b>	Fr.R.	<b>Fulda: 5 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	246,56
-------------------	--------

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Wing R R, Scratch(es), LI - Repair and paint (complete)	246,56
---	--------



Door F R, Scratch(es), LI - Repair and paint (complete)	0,00
---	------



Wheel cover R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Door R R, Scratch(es), LI - Repair and paint (complete) 0,00



Bumper F, Scratch(es), Acceptable 0,00

*No pictures to display*