



RENAULT MASTER: 1CRE268

Vinnumber:	VF1MAF4YE54425884	Versionname:	
First Registrationdate:	14/01/2016	Fiscalpower:	
Expertise Mileage:	57022	Power Kw:	100
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	TRU13
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/65/16/112 R Steel			
Summer tyres:	Fr.L.	Michelin: 1 mm	Fr.R.	Michelin: 1 mm
	Re.L.	Continental: 2 mm	Re.R.	Continental: 2 mm

Assistance equipment

Total cost ex VAT	1968,32
Wheel cover F L, Missing, E - Replace	22,50



Rearview mirror housing L, Broken, LI - Repair and paint (complete)	115,56
---	--------



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearlight L, Broken, E - Replace 91,50



Wheel cover R R, Missing, E - Replace 22,50



Bumper R, Crack, E - Replace 329,40



Rearview mirror glass R, Broken, E - Replace 13,50



Wing F L, Scratch(es), LI - Repair and paint (complete) 165,13



Wheel cover F R, Missing, E - Replace 22,50



Trunk door R L, Dent(s) and scratch(es), It - Spot repair 115,56



Door R R, Dent(s), LI - Repair and paint (complete) 238,76



Bonnet, Dent(s), LI - Repair and paint (complete) 217,56



Wheel cover R L, Missing, E - Replace

22,50



Wing R L, Scratch(es), LI - Repair and paint (complete)

231,15



Bumper F, Scratch(es), Smart repair

110,64



Bumper moulding R L, Scratch(es), E - Replace

10,80



Door R L, Scratch(es), LI - Repair and paint (complete)

238,76

