



VOLKSWAGEN TIGUAN: 1ETC803

Vinnumber:	WVGZZZ5NZDW601852	Versionname:	TIGUAN Sport & Style BM Tech.110PK
First Registrationdate:	14/03/2013	Fiscalpower:	
Expertise Mileage:	147631	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel		
Maintenance:	NOT OK		
Maintenance:	UITVOEREN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Battery functioning	Yes
---------------------	------------

Degree of wear

Winter tyres:	235/55/17/99 H LightMetal			
	Fr.L.	Dunlop: 7 mm	Fr.R.	Dunlop: 7 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	421,76
-------------------	---------------

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door frame R R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Grill frame, Hole, E - Replace	80,00
--------------------------------	--------------



Bumper moulding F M, Scratch(es), E - Replace	14,40
---	--------------



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Maintenance, Maintenance, Execute 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Bodywork, Not original part, P - Check 0,00

