



## SKODA Octavia: 1HAU137

Vinnumber:	<b>TMBJG7NE4E0229317</b>	Versionname:	<b>OCTAVIA COMBI Ambition</b>
First Registrationdate:	<b>5/06/2014</b>	Fiscalpower:	<b>105PK</b>
Expertise Mileage:	<b>131945</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3125</b>
Maintenance:	<b>IN 18200KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/55/16/91 V Steel</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 3 mm</b>	Fr.R.	<b>Bridgestone: 3 mm</b>
	Re.L.	<b>Bridgestone: 7 mm</b>	Re.R.	<b>Bridgestone: 7 mm</b>

## Assistance equipment

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>387,36</b>
-------------------	---------------

Rearview mirror housing R, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

No pictures to display

Bonnet, Stone chip(s), Acceptable	<b>0,00</b>
-----------------------------------	-------------

No pictures to display

Wheel cover F R, Missing, E - Replace	<b>30,00</b>
---------------------------------------	--------------



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Windscreen, Stone chip(s), Windscreen repair 0,00




Wing F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Door frame R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Rear window, Scratch(es), E - Replace 0,00



Wheel cover F L, Missing, E - Replace 30,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80

