



## VOLKSWAGEN Golf: 1HPS691

Vinnumber:	<b>WVWZZZAUZFW077518</b>	Versionname:	<b>GOLF BER Highline 105PK</b>
First Registrationdate:	<b>8/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>109959</b>	Power Kw:	<b>77</b>
Bodytype:		Body color	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>3506</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

## Options

Radio CD		Central consol F
GPS storage	<b>SD</b>	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/55/16/92 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

## Assistance equipment

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>383,70</b>
-------------------	---------------

Bumper R, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

No pictures to display

Door F L, Dent(s), PDR - Knock out without painting	<b>63,00</b>
---	--------------



Bonnet, Scratch(es), Acceptable	<b>0,00</b>
---------------------------------	-------------

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)	<b>308,20</b>
---	---------------



Seat cover R, Stain, Cleaning	12,50
-------------------------------	-------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*