


PEUGEOT 807: 1HLF937

Vinnnumber:	VF3EBRHD8EZ030199	Versionname:	807 Style FAP 136PK
First Registrationdate:	19/08/2014	Fiscalpower:	
Expertise Mileage:	157978	Power Kw:	100
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2215
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 V LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Emergency spare wheel	Yes
-----------------------	------------

Total cost ex VAT	1712,22
Rearview mirror housing L, Missing, Le - Replace and paint	115,00



Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Bumper grille, Crack, E - Replace 34,08



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16



Roof, Chemical pollution, LI - Repair and paint (complete) 577,80



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), Acceptable 0,00

No pictures to display