



AUDI Q7: 1HVH516			
Vinnumber:	WAUZZZ4L7FD000579	Versionname:	Q7 S-line St/St Tiptr.245PK Aut.
First Registrationdate:	13/10/2014	Fiscalpower:	
Expertise Mileage:	154348	Power Kw:	180
Bodytype:	MPV	Body color:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2315
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	295/40/20/110 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment	
Total cost ex VAT	2401,97
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Door F R, Scratch(es), LI - Repair and paint (complete)	382,02
---	---------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16




Door R R, Scratch(es), LI - Repair and paint (complete)

382,02



Wing R R, Scratch(es), LI - Repair and paint (complete)

369,84



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00





Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Scratch(es), LI - Repair and paint (complete)

264,21



Rearview mirror housing R, Bad repair, LI - Repair and paint (complete)

115,56

