


BMW 3: 1GKJ813

Vinnumber:	WBA3Y11060D448923	Versionname:	3 GRAN TURISMO 318d
First Registrationdate:	3/03/2014	Fiscalpower:	136PK
Expertise Mileage:	144815	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4223
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 1,8 mm	Re.R.	Michelin: 1,8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT **423,60**

Door F R, Scratch(es), Acceptable **0,00**

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) **211,80**



Seat cover F L, Damaged, Acceptable **0,00**



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Rocker panel inner R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Windscreen, Repaired, Acceptable	0,00
----------------------------------	------



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display