


AUDI A1: 1HAN265

Vinnnumber:	WAUZZZ8X8EB120947	Versionname:	A1 5B Attraction 90PK
First Registrationdate:	4/06/2014	Fiscalpower:	
Expertise Mileage:	175913	Power Kw:	66
Bodytype:		Body color	Dark Blue
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2106
Maintenance	IN 4100 KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Sun Roof electric
GPS storage	Central consol F
GPS storage	SD Luggage cover
Windows electric F	Rear parking sensors
Windows electric R	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Level control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/15/88 V LightMetal			
Summer tyres:	Fr.L.	Fulda: 6 mm	Fr.R.	Fulda: 6 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
		Jack	Yes

Total cost ex VAT	570,30
Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing R L, Scratch(es), Acceptable 0,00



Bumper R, Dent(s) and scratch(es), Acceptable 0,00



Door F R, Scratch(es), Acceptable 0,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Door R R, Scratch(es), Acceptable 0,00



Bumper F, Scratch(es), Acceptable 0,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 244,18



Bonnet, Dent(s) and scratch(es), Acceptable 0,00



Roof, Dent(s), Acceptable 0,00

