



**FORD FIESTA: 1AX0030**

Vinnumber:	<b>WFORXXGAJRB01806</b>	Versionname:	
First Registrationdate:	<b>1/01/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>151061</b>	Power Kw:	
Bodytype:	<b>Transporter</b>	Body color	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2223</b>
Number of doors	<b>3</b>		
Number of seats	<b>2</b>		
Number head rests	<b>2</b>		
Rims summer	<b>Steel</b>		
Category	<b>Light Commercial Vehicle</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>No</b>		

**Options**

Radio CD		Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>NOT OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/50/15/82 V Steel</b>			
Summer tyres:	Fr.L.	<b>Other: 6 mm</b>	Fr.R.	<b>Other: 6 mm</b>
	Re.L.	<b>Other: 7 mm</b>	Re.R.	<b>Other: 7 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	2091,56
Wheel cover R R, Scratch(es), E - Replace	24,00



Registration Document, Missing, E - Replace	150,00
---	--------

No pictures to display

Wheel cover R L, Scratch(es), E - Replace	24,00
---	-------



Gear shift lever cover, Tear, E - Replace 9,60



Wheel cover F L, Scratch(es), E - Replace 24,00



Floor covering F L, Damaged, E - Replace 240,00



Inner seat cover L, Broken, Smart repair 110,64



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Rearlight R , Broken, E - Replace 96,00



Backrest cover F L, Hole, E - Replace 312,00



Bumper R, Crack, Smart repair 110,64



Interior, Dirty, Cleaning 100,00



Certificate Of Conformity, Missing, E - Replace	150,00
---	--------

*No pictures to display*

Wheel cover F R, Missing, E - Replace	24,00
---------------------------------------	-------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

*No pictures to display*

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,68
---	--------





Seat cover F L, Damaged, E - Replace

312,00

