



BMW 1: 1FRR619

Vinnumber:	WBA1C91090J517013	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	3/10/2013	Fiscalpower:	
Expertise Mileage:	79340	Power Kw:	85
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3531
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/92 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm


Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	371,20
Bonnet, Bad repair, Acceptable	0,00



Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
---	---------------



Wing R L, Bad repair, Acceptable 0,00



Door R L, Bad repair, Acceptable 0,00



Wing R R, Bad repair, Acceptable 0,00



Bumper R, Bad repair, Acceptable 0,00



Door R R, Dent(s), PDR - Knock out without painting 63,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 0,00



Tailgate, Bad repair, Acceptable 0,00

