


BMW X5: 1PFH042

Vinnnumber:	WBAKS410200R84628	Versionname:	
First Registrationdate:	22/06/2016	Fiscalpower:	
Expertise Mileage:	89845	Power Kw:	190
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	4 Weel	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	-2000KM	Parking lot	3710
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunction			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	255/50/19/107 Y LightMetal			
Summer tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Repair kit	No	Compressor	No
Total cost ex VAT			952,80
Door frame F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			95,00



Door F R, Dent(s), PDR - Knock out without painting	63,00
---	-------



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Tyre repair kit, Missing, E - Replace	252,64
---------------------------------------	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Maintenance, Maintenance, Execute	0,00
-----------------------------------	------



Wing R L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Luggage space cover, Missing, E - Replace	288,00
---	--------

