


LAND ROVER RANGE ROVER EVOQUE: 1GS167

Vinnumber:	SALVA2BC4EH935674	Versionname:	TD4 4WD Dynamic
First Registrationdate:	15/04/2014	Fiscalpower:	
Expertise Mileage:	139699	Power Kw:	110
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	4 Weel	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2312
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Panoramic roof
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/55/19/105 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2086,10
-------------------	----------------

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------





Door F L, Scratch(es), It - Spot repair

115,56



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Dent(s), Acceptable

0,00

No pictures to display

Bumper R, Broken, Le - Replace and paint

766,80



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Interior, Not original part, P - Check

0,00



Wing F L, Scratch(es), LI - Repair and paint (complete)

264,21



Wing moulding F L, Scratch(es), E - Replace

17,28



Tailgate, Scratch(es), It - Spot repair

115,56





Rearlight L, Broken, E - Replace	132,00
----------------------------------	--------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Roofrack, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Interior, Not original part, E - Replace	100,00
--	--------



Bumper Trim F, Dent(s) and scratch(es), E - Replace	113,13
---	--------



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Foglight L, Broken, E - Replace	156,00
---------------------------------	--------



Tailgate, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display