




FORD Mondeo: 1GSN277				
Vinnumber:	WF0GXXG8BGET45341	Versionname:	MONDEO CLIP ECO Titanium Style 136PK	
First Registrationdate:	16/04/2014	Fiscalpower:		
Expertise Mileage:	183259	Power Kw:	100	
Bodytype:	Break	Body color	Grey	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:		Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	3113	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
Windows electric F		Luggage cover		
Windows electric R		Front parking sensors		
Cruise Control		Rear parking sensors		
Steering wheel multifunctional		Type of Tow bar	No Tow bar	
Seats F heated				
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Summer tyres:	215/60/16/99 V LightMetal			
	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Assistance equipment				
Spare wheel	Yes			
Total cost ex VAT			915,23	
Wing F R, Scratch(es), LI - Repair and paint (complete)			0,00	
				
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)			95,00	



Bonnet, Scratch(es), LI - Repair and paint (complete)	290,08
---	--------



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00
---	------



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)	0,00
---	------



Tailgate, Scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	