



## VOLKSWAGEN Golf: 1HNY660

Vinnnumber:	<b>WVWZZZAUZFP534931</b>	Versionname:	<b>GOLF VAR Trendline 105PK</b>
First Registrationdate:	<b>2/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>133491</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2609</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	<b>No Tow bar</b>
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>NOT OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>NOT OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

195/65/15/91 T LightMetal				
Winter tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 8 mm</b>	Re.R.	<b>Michelin: 8 mm</b>

## Assistance equipment

Emergency spare wheel	<b>Yes</b>
-----------------------	------------

Total cost ex VAT	750,33
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35





Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18

